



QUADRO DE CARGA								
CIRC	PONTO DE LUZ			TOMADAS		CARGA TOTAL	COND. (mm2)	DIS(A)
	60	100		100	300			
1	11					660	1,5	15A-1
2		10				1000	2,5	20A-1
3			3	2		900	2,5	20A-1
4		1				400	2,5	40A-1
5				1	1	600	2,5	20A-1
6						700	2,5	20A-1
7						420	1,5	15A-1
8*			3	2		900	2,5	20A-1
9						600	2,5	20A-1
10				1	1	700	2,5	20A-1
11*						60	1,5	15A-1
FC1						300	2,5	20A-1
FC2				1		300	2,5	20A-2
TOTAL DO QDL APTOS 01/02/11/12						7540	6,0	40A-40A

(*) FORA DO ECONOMIZADOR

QUADRO DE CARGA										
CIRC	PONTO DE LUZ		TOMADAS				CARGA TOTAL (W)	COND. (mm ²)	DISU(A)	
	80	100	100	300	600	1200				
1	10						600	1,5	15A-1	P
2			10				1000	2,5	20A-1	P
3*			3	2			900	2,5	20A-1	P
4			1	1			400	2,5	20A-1	P
5					1		600	2,5	20A-1	P
6			1	1			700	2,5	20A-1	P
7	8						480	1,5	15A-1	P
8*			3	2			900	2,5	20A-1	P
9			6				600	2,5	20A-1	P
10			1	1			700	2,5	20A-1	P
11*							60	1,5	15A-1	P
FC1				1			300	2,5	20A-2	P
FC2				1			300	2,5	20A-2	P

TOTAL TOTA DO QD. APTOS 03/04/05/06/07/08/09/10 DR-40A-4P

(*) FORA DO ECONOMIZADOR

QUADRO DE CARGA								
CIRC	PONTO DE LUZ		TOMADAS			CARGA TOTAL (W)	COND. (mm2)	DIS(A)
	01	02	100	300	600			
S. a	9	(0001A)				540	1,5	15A-1
S. a	9	(0001B)				540	1,5	15A-1
S. a	9	(0001C)				540	1,5	15A-1
S. b	9	(0001A)				540	1,5	15A-1
S. b	9	(0001B)				540	1,5	15A-1
S. b	9	(0001C)				540	1,5	15A-1
S. c	4	(0001A)				240	1,5	15A-1
S. c	4	(0001B)				240	1,5	15A-1
S. c	4	(0001C)				240	1,5	15A-1
T			10	(001A)		1000	2,5	20A-1
T			10	(001B)		1000	2,5	20A-1
RS1			10	(001C)		1000	2,5	20A-1
RS2					800	800		
RS3					800	800		
TOTAL DO QDLN-5/8/11/14/17 E 20						9360	6,0*	-
* 10,0 PARA OS QDLN-11/14/17 E 20								

CIRC	PONTO DE LUZ		TOMADAS		CARGA TOTAL (W)	COND. (mm2)	DIS(A)
	60	100	300	600			
V	10	(pot. A)			600	1,5	15A-1F
V	10	(pot. B)			600	1,5	15A-1F
V	10	(pot. C)			600	1,5	15A-1F
RS1					600	1,5	15A-1F
RS2					600	1,5	15A-1F
RS3					600	1,5	15A-1F
TOTAL DO QDLNE-5/8/11/14/17 E 20					3600	2,5*	20A-3F

* 3X4,0 PARA OS QDLNE-14/17 E 20

[illegible]